

Storage information for self-adhesive labels

These tips will help you to keep the functionality and look of your self-adhesive labels:

- protect the labels from **direct sunlight** and **heat** (for example radiators)
- store the labels **dry** and **cool** until the converting
- optimal storage temperature is from **20°C to 24°C**
- relative humidity between **45% and 55%**
also optimal processing conditions
- store the labels **lying flat** and **centred over each other**
- **no external pressure** (for example tight boxes)
- the storage location should not be subjected to large variations in temperature
- if labels come from a space with significantly different climatic conditions or from the carrier, then it is ideal to **acclimatise** the labels **24 hours** before processing

